Drain

Particulars of side Drains

Left

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered BS Slabs		BS Slab		West

Other Flow Direction Type	Length (m)	Average Width(m)
	105.00	0.60

Right

Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
Covered BS Slabs		BS Slab		West

Other Flow Direction Type	Length (m)	Average Width(m)
	105.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
RCC deck slab		4.50	1.80

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	2
Others			

Inspection Details

Number of Trees 0

Date of Inspection 17/07/2015

Name nagabhushan

Remarks

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

19

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0066	NA	near aswath katte
Unique Road No.	**Length of full Road(m)**	
13-W0066-10378	45.00	

Road Details

Road From	Road To
near aswath katte	dead end
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
40.00	6.10			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	Covered BS Slabs		BS Slab		East

Other Flow Direction Type	Length (m)	Average Width(m)
	40.00	0.60

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	Covered BS Slabs		BS Slab		East

Other Flow Direction Type	Length (m)	Average Width(m)
	40.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
RCC deck slab		5.00	1.80

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	1
Others			

Inspection Details

Number of Trees 0

Date of Inspection 17/07/2015

Name nagabhushan

Remarks

Any Other Information

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road Inventory Form

General

Zone	Ward No.	Ward Name
DASARAHALLI	13	Mallasandra
Street ID	**Street Name**	**Significant Landmark**
W0070	NA	AshWath katte
Unique Road No.	**Length of full Road(m)**	
13-W0070-10377	51.00	

Road Details

Road From	Road To
AshWath katte	dead end
Type of Road	**Other Road Type**
Others	minor

Chainage at point (m)	Measured Width (m)	Existing Surface	Other Existing Surface	Remarks
48.00	6.00			

Footpath

☐ Left

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

☐ Right

chainage at the point(m)	Type of Footpath	Other Footpath Type	Length (m)	Average Width(m)	No of Shoulder Drain	Kerb Chainages (m)	Remarks
	No Footpath		0.00	0.00	0	0.00	

Drain

Particulars of side Drains

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Left	Covered BS Slabs		BS Slab		East

Other Flow Direction Type	Length (m)	Average Width(m)
	48.00	0.60

	Drain Type	Other Drain Type	Construction Type	Other Construction Type	Flow Direction
☐ Right	Covered BS Slabs		BS Slab		East

Other Flow Direction Type	Length (m)	Average Width(m)
	48.00	0.60

Culvert / Cross-Drainage details

Type of Culvert	Other Culvert	Length/Span according to road width(m)	Width (m)
RCC deck slab		6.10	1.80

Existing Services

BESCOM	yes	**BWSSB**	yes
OFC		**Manholes**	2
Others			

Inspection Details

Number of Trees 0

Date of Inspection 17/07/2015

Name nagabhushan

Remarks

Any Other Information

Category	Image	Photo Remark
Road Condition		
Segment End		
Segment Start		